


FAIRMILE RESTORATIONS

Historic vehicle bodywork specialist.

Iain McKenzie

**Restoration services, panel making, one offs, small batches etc
Original panels repaired, Minor LCV specialist.**



Unit B3,
Green Business Centre,
Stanford Bridge,
Worcestershire
WR6 6SA
07971 424396
Fax only 01584 819495

This is a sample of some of the panels I can supply for Morris Minors. All the usual panels can be supplied as well, and I provide a restoration service for unobtainable panels such as pickup sides, tailgates and doors

M01	Van/pickup rear inner arches. Heavy gauge steel, and a very good match to the originals	£55
M02	Van/pickup rear half floor. Available separate or spot welded to the arch	£45
M03	Rear light 1/4 panel. Full panel from wheel arch to rear lights.	£18
M03a	As above, but for early single light model, with shaped rear corner	£27
M04	Body side front end repair. From front of rear wheel arch to B post (normally 15" high but can be supplied different heights if req)	£18
M05	Van body, rear top corner repair section	£22
M06	Van body top of side repair section	£18
M07	Guttering straight length	£12
M08	Guttering corner piece	£12
M09	Cab guttering, formed to correct shape 1 length to do one side	£18
M09a	As above but Series 2 squarer profile	£24
M10	Sill boxing plate van/pickup	
M11	Under sill panel for van/pickup with correct flanges all round (unlike other pattern panels)	£22
M15	Pickup cab back repair panel	£25
M18	Front flitch extension—all types early or late series 2 and Minor 1000	£7
M19	Radiator cowl, lower repair section (all types)	£18
M25	Folded steel Metro seat subframes to suit saloons/travellers	£25
M25a	Folded steel Metro seat subframes to suit vans/pickups	£20
M30	Front inner wheel arch. Full domed section (accurate fit based on BMC original)	£67
M30a	Front inner wheel arch. Rear section only for repairing original panel	£24
M40	Steel exterior sunvisor	£130
M45	Mudflap brackets for PO vans (recommended for all vans/pickups. Galvanised steel)	£15pr

(trade prices available for any quantity ordered) (no vat on above prices)

Sample Prices for Repair Services

Pickup sides inc all panels from £150 per side depending on condition.

Tailgates £40—£170 depending on cond.

Door bottom rebuild and outer skin
£125

Van body rebuild; bottom edges, cross-members, floors and inner arches etc £900

Typical cab rebuild inc floors sills B post hinge pillar repairs etc, built up on a jig. Shot blasted and primed if req. £700—£1100

All prices are a general guide and depend very much on condition of the supplied components

